

Docket No.: S1022.81108US00  
(PATENT)

**IN THE UNITED STATES PATENT AND TRADEMARK OFFICE**


Applicant: Hilal Ezzeddine et al.  
Serial No.: 10/729,682  
Confirmation No.: 3164  
Filed: December 5, 2003  
Patent No.: 7,394,333  
For: DIRECTIONAL COUPLER

Examiner: D. O. Takaoka  
Art Unit: 2817

**Certificate of Electronic Filing Under 37 CFR 1.8**

I hereby certify that this paper (along with any paper referred to as being attached or enclosed) is being transmitted via the Office electronic filing system in accordance with § 1.8(a)(4).

Dated: July 10, 2008

  
Gail Driscoll

**REQUEST FOR CERTIFICATE OF CORRECTION PURSUANT TO 37 CFR 1.322**

Attention: Certificate of Correction Branch  
Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

Dear Sir:

Upon reviewing the above-identified patent, Patentees noted a typographical error which should be corrected.

**In the Specification:**


At column 2, line 22, the terminal identifier "IN" has been changed to read "iN". Terminal identifier "IN" can be found elsewhere in the application. Specifically, terminal identifier IN can be found on page 1, line 12 and on page 2, line 24 as well as on Figs. 1-4.

No amendment was made by either the Examiner or Patentees changing terminal identifier "IN" to "iN". Therefore, the error identified above was not the fault of Patentees, accordingly it is believed that no fee is required. However, should the Examiner determine a fee to be necessary, the fee should be charged to the deposit account of the undersigned, Deposit Account No. 23/2825.

Transmitted herewith is a proposed Certificate of Correction effecting such amendment.  
Patentee respectfully solicits the granting of the requested Certificate of Correction.

Dated: July 10, 2008

Respectfully submitted,

By:  \_\_\_\_\_

James H. Morris  
Registration No.: 34,681  
WOLF, GREENFIELD & SACKS, P.C.  
Federal Reserve Plaza  
600 Atlantic Avenue  
Boston, Massachusetts 02210-2206  
617.646.8000

**UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION**

Page 1 of 1

PATENT NO. : 7,394,333  
APPLICATION NO. : 10/729,682  
ISSUE DATE : July 1, 2008  
INVENTOR(S) : Hilal Ezzeddine et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. 2, line 22 should read:  
respectively connecting terminals IN and CPLD and ter-

MAILING ADDRESS OF SENDER (Please do not use customer number below):

James H. Morris  
WOLF, GREENFIELD & SACKS, P.C.  
Federal Reserve Plaza  
600 Atlantic Avenue  
Boston, Massachusetts 02210-2206

1